KAT Nexus Firmware Update Guide

Preparation:

1,USB Male-to-Male Cable



2,Software and image file

Download link:

https://drive.google.com/file/d/19KO6_ctOcTyiTZAgz0NkcBbFFNiGPZQG/view?us

p=sharing

Firmware Update

1, Download the file from the link above and unzip it to your computer.



杭州虚现科技有限公司 Copyright © 2017 Hangzhou Virtual And Reality Technology Co., LTD.



2,Open the DriverAssitant_v5.1.1 folder and run DriverInstall.exe



杭州虚现科技有限公司 Copyright © 2017 Hangzhou Virtual And Reality Technology Co., LTD.

KNTVR

RK Driver Assitant v5.1.1	×
Install DriverInstall DriverInstall DriverInstall DriverInstall Driver ok.	× 1 Driver

Now you have successfully installed the driver, you can close the software.

3, Open the FactoryTool folder and run FactoryTool.exe

Date modified	Туре	Size
3/24/2023 1:08 PM	File folder	
3/24/2023 1:08 PM	File folder	
12/30/2022 10:34 AM	File folder	
1/11/2021 8:09 PM	Configuration sett	4 KB
1/28/2021 11:23 AM	Application	1,969 KB
12/30/2022 12:20 PM	Configuration sett	1 KB
1/27/2021 4:55 PM	Text Document	1 KB
	Date modified 3/24/2023 1:08 PM 3/24/2023 1:08 PM 12/30/2022 10:34 AM 1/11/2021 8:09 PM 1/28/2021 11:23 AM 12/30/2022 12:20 PM 1/27/2021 4:55 PM	Date modified Type 3/24/2023 1:08 PM File folder 3/24/2023 1:08 PM File folder 3/24/2023 1:08 PM File folder 1/230/2022 10:34 AM File folder 1/11/2021 8:09 PM Configuration sett 1/28/2021 11:23 AM Application 12/30/2022 12:20 PM Configuration sett 1/27/2021 4:55 PM Text Document

4, Click Firmware Button



actoryTool(Release Vesion) v1.72.	2					- 🗆	×
Firmware Run	⊙ Upgrade ○ Restore	Demo	Lang	Jage 🔶 Exit			
				Firmware Ver:			
rmware				Lorder Ver			
				Loader ver.			
Jemo				Chip:			
ID Fail	 Device List 	Device Type	ID	Upgrade Prompt	ID	Success	
	🖃 🛒 My Computer				^		_
	RootHub20						
					_		
\					_		
N N							
	Port[4]						
	Port[6]				_		
					-		
	Port[8]				-		
	RootHub20						
	Port[1]				-		
	Port[2]				-		
	Port[5]				-		
	Port[4]				-		
	Port[6]				-		
	Port[7]				-		
					~		
	< <				>		
	< <				>		
zard:							
.First use,Tag USB port:	plug device in, record ID	showing on the to	ol.Tag all.		Success:	0	
After pluging device in	, connect another until de	vice is doing upg	rade.				
B.led is green, plug devic	e in;led is red, do not pl	ug device in or o	ut.		Fail:	0	
	groop to show sussess to	d to show failure				0	
4.After finishing upgrade	, green to show success, re	a co snow rarrare			Tehe		

,Find the path	n you downloa	aded and select	the img file	,click Open.			
🌒 Open						\times	ł.
Look <u>i</u> n:	update		~	G 🌶 🖻 🛄 -			1
Quick access Desktop Libraries	Name DriverAssita FactoryTool	nt_v5.1.1 firmware		Date modified 3/24/2023 1:08 PM 3/24/2023 1:08 PM 11/9/2022 12:28 A	1 1 M	Type File fc File fc Disc I	Is. Yb.
Network	< File <u>n</u> ame: Files of <u>type</u> :	Firmware(*.img)/Load	der(*.bin)	~ [~	<u>O</u> pe Can	> n cel	1

6,Wait a few seconds until the img is loaded.



FactoryTool(Rele	ase Vesion) v1.72.2						-
Firmware	Run R	● Upgrade ○ Restore	Demo	Lar	nguage 🔿 Exit		
		hug KAT Namus 11 20221100 /	0014 ing		Firmware Verth.(1. 00	
Firmware D. up	late (Kh3516_userde)	Dug_RAI_Nexus_II_20221109.	0014.1mg		Looder Ver: 2, 22		
Demo					Chine PK200		
					Chip:KK322H		
ID	Fail	Device List	Device Type	ID	Upgrade Prompt		D Succe
		B My Computer				^	
		RootHub20				- 11	
		Port[1]				- 11	
		Port[2]				- 11	
		Port[4]				- 11	
		Port[5]					
		Port[6]					
		Port[7]					
		RootHub20					
		Port[1]					
		Port[3]				_	
						_	
		Port[5]				_	
						_	
						_	
		Port[8]					
						~	

7, Change option Update to Restore, then click Run button.

6		1 A					
actoryTool(Release Vesion)	v1.72.2	_	,			- 0	
Firmware rmware Demo	Run Upgrade Restore	0014. img	Langu	Exit Firmware Ver:b.0.00 Loader Ver:2.32 Chip:RK322H			
ID Fail	Device List	Device Type	ID	Upgrade Prompt	ID	Success	
	Image: Wight RootHub20 Image: Wight RootHub				~		
izard:		-h	-1 711		Success	. 0	
2.After pluging devic	ce in, connect another until d	showing on the to evice is doing upg	oi.lag all. rade.		Juccess		
3.led is green,plug o	device in;led is red,do not p	lug device in or o	ut.		Fail:	0	
4.After finishing upg 5.To show successful	grade, green to show success, r device on the right of grid :	ed to show failure and failed device	on the left	of grid.	Total:	0	
K''	A				-	2	_



FactoryTool(Releas	ie Vesion) v1.72.2	Restore	Demo	Language	Exit	-	
Firmware D:\upda	ite\RK3318_usero.ug_KAT_Nexu	s_11_20221109.0014. ir	ng		Firmware Ver:b.0.00 Loader Ver:2.32		
			a : a	12	Chip:RK322H		
		Evice List omputer soft-lub20 > Port[1] > Port[2] > Port[3] > Port[4] > Port[5] > Port[5] > Port[6] > Port[7] > Port[8] oorHub20					255
Vizard:	× ×	 Port[3] Port[3] Port[4] Port[5] Port[6] Port[7] Port[8] Port[8] 			>		, , , , , , , , , , ,
1.First use, Ta	ag USB port:plug device :	n, record ID showi	ng on the too	l.Tag all.		Success: 0	
2. After plugir	ng device in, connect anot	her until device	is doing upgr	ade.		Fail: 0	
3.led is greer 4.After finish	n,plug device in;led is r hing upgrade,green to sha	ed, do not plug de ow success, red to	evice in or ou show failure.	t.		Tetal.	
5.To show succ	cessful device on the rig	ht of grid and fa	ailed device of	n the left of	grid.	Iotal. V	
				4	18-		
FactoryTool(Releas	se Vesion) v1.72.2					-	×
Firmware Divução	Stop Upgrade	Restore 11_20221109.0014.it	Demo	Language	Exit Firmware Ver: b. 0.00 Loader Ver: 2.32		
					Chip:RK322H		
		evice List icomputer icomputer icontHub20 > Port[1] > Port[2] > Port[3] > Port[6] > Port[6] > Port[6] > Port[7] > Port[7] > Port[1] > Port[1] > Port[2] > Port[1] > Port[2] > Port[4] > Port[5] > Port[5] > Port[5] > Port[6] > Port[6] > Port[6] > Port[7] > Port[8] > Port[9]	Device Type		Chip: RK322H Upgrade Prompt	ID Succ	255
ID F	Fail D Fail D	evice List iomputer ootHub20 > Port[1] > Port[2] > Port[3] > Port[6] > Port[6] > Port[6] > Port[6] > Port[7] > Port[8] > Port[1] > Port[1] > Port[1] > Port[2] > Port[3] > Port[4] > Port[5] > Port[6] > Port[6] > Port[6] > Port[7] > Port[8] > Port[9] Dot Fort[9] Dot	Device Type	ID	Chip: RK322H Upgrade Prompt	ID Succ Success: 0	295
ID F Fizard: 1. First use, Ta 2. After plugir	ag USB port: plug device in connect and	evice List iomputer iomp	Device Type	ID	Chip: RK322H Upgrade Prompt	ID Succ Success: 0 Fail: 0	295
ID F Vizard: . 1. First use, Ta 2. After plugir 3. led is greer 4. After finish	Fail D Fail D	<pre>eviceList icomputer oorHub20 > Port[1] > Port[2] > Port[2] > Port[3] > Port[4] > Port[6] > Port[6] > Port[6] > Port[7] > Port[7] > Port[7] > Port[1] > Port[7] > Port[4] > Port[7] > Port[6] > Port[7] > Port[6] > Port[7] > Port[8] > Port[9] n, record ID showi her until device ed, do not plug de w success, red to</pre>	Device Type Ing on the too is doing upgrevice in or our show failure.	ID	Chip: RK322H	ID Succ Success: 0 Fail: 0 Total: 0	255
ID F Vizerd: . 1. First use, Ta 2. After plugir 3. led is greer 4. After finish 5. To show succ 5. To show succ	Fail D Fail D	<pre>eviceList icomputer oorHub20 > Port[1] > Port[2] > Port[3] > Port[4] > Port[6] > Port[6] > Port[6] > Port[7] > Port[7] > Port[8] > Port[1] > Port[2] > Port[1] > Port[2] > Port[5] > Port[5] > Port[6] > Port[6] > Port[6] > Port[7] > Port[7] > Port[8] > Port[8] > Port[9] n, record ID showi her until device ed, do not plug de w success, red to ht of grid and fa</pre>	Device Type Ing on the too is doing upgr vice in or our show failure.	ID	Chip: RK322H Upgrade Prompt	ID Succ Success: 0 Fail: 0 Total: 0	295
ID F Vizard: 1.First use, Ts 2.After plugir 3.led is greer 4.After finish 5.To show succ	Fail D Fail D	<pre>eviceList icomputer oorthub20 > Port[1] > Port[2] > Port[3] > Port[4] > Port[6] > Port[6] > Port[6] > Port[7] > Port[7] > Port[1] > Port[1] > Port[1] > Port[3] > Port[6] > Port[6] > Port[6] > Port[7] > Port[6] > Port[7] > Port[8] > Port[9] > Port[9] > Port[9] = Port[9] = Port[9] > Port[9] = Port[9] =</pre>	Device Type Ing on the too is doing uppr vice in or our show failure. hiled device ou	ID	Chip: RK322H Upgrade Prompt	ID Succ Success: 0 Fail: 0 Total: 0	
ID F Vizard: 1. First use, Ta 2. After plugir 3. led is greer 4. After finist 5. To show succ	Fail D Fail D	<pre>eviceList icomputer ootHub20 > Port[1] > Port[2] > Port[3] > Port[4] > Port[6] > Port[6] > Port[7] > Port[7] > Port[7] > Port[7] > Port[7] > Port[7] > Port[6] > Port[7] > Port[6] > Port[7] > Port[7] > Port[6] > Port[9] n, record ID showi her until device ed, do not plug de w success, red to ht of grid and fa</pre>	Device Type Ing on the too is doing upgr vvice in or our show failure. wiled device of	ID	Chip:RK322H Upgrade Prompt	ID Succ Success: 0 Fail: 0 Total: 0	

KNTVC

8,Now we need to connect the KAT Nexus to the computer , Plug the USB male-to-male cable into the black USB socket of the KAT Nexus, but do not connect it to the computer for now.









9,There is a reset button in the AV socket of KAT Nexus, use a toothpick or pin to insert the AV port and keep pressing it, Make sure you hear a click,then plug the USB cable into the computer without releasing the Reset button





10, After plugging the USB cable into the computer, the software will run





actoryTool(Release Vesion) v1.72.2	Upgrade ® Restore	Demo	Languag	e 🔶 Exit	4	x	<
rmware D:\update\RK3318_usero	jebug_KAT_Nexus_11_20221109.00	14. img		Firmware Ver:b.0 Loader Ver:2.32 Chin:RK322H	. 00		
D Fail	Device List	Device Type	ID	Upgrade Prompt	ID	Success	
	My Computer				^		14
	Port[2]						
	Port[4]						
	RootHub20						
	Port[2]						R
	Port[6]	Maskrom	13	Erase Flash(29%)			
	Port[8]						
	<				>	~	·
To show successful devic	e on the right of grid and	d failed device	on the left of	grid.	Intal.	U	
		Th				12	
						- U X	
toryTool(Release Vesion) v1.72.2		Dama		. Strit			
toryTool(Release Vesion) v1.72.2	○Upgrade ◎ Restore	Demo	Languag	e Exit	00		
toryTool(Release Vesion) v1.72.2 Firmware Stop nware D.\update\RK3318_usero	Upgrade © Restore	Demo 14. img	Languag	e Exit Firmware Ver:b.O Loader Ver:2.32	. 00		
toryTool(Release Vesion) v1.72.2	Upgrade © Restore	Demo	Languag	Exit Firmware Ver: b. 0 Loader Ver: 2. 32 Chip: RK322H	. 00		
toryTool(Release Vesion) v1.72.2 Firmware Stop wware D. update/RX3018_usere amo Fail	Upgrade © Restore debug KAT_Nexus_11_20221109.00 Device List	Device Type	ID Languag	Exit Firmware Ver: b. 0 Loader Ver: 2. 32 Chip: RK322H Upgrade Prompt	. 00 ID	Success	KIS.
toryTool(Release Vesion) v1.72.2 Firsware Stop nware 7. Update) RX3318_user emo D Fail	Upgrade © Restore 3ebug_KAT_Nexus_11_20221109.00 Device List □ ₩ Computer ↓ WF RoatHub20	Device Type	ID Languag	Exit Firmware Ver: b. 0 Loader Ver: 2, 32 Chip: RK322H Upgrade Prompt	. 00 ID	Success	X b
toryTool(Release Vesion) v1.72.2	Device List Wy Computer Wy	Device Type	ID Languag	Exit Firmware Ver: b. 0 Loader Ver: 2. 32 Chip: RK322H Upgrade Prompt	. 00	Success ^	
toryTool(Release Vesion) v1.72.2	Upgrade Restore List Device List Wy Computer Wy RootHub20 Port[1] Port[2] Port[3]	Demo	Inguage Language	Exit Firmware Ver: b. 0 Loader Ver: 2. 32 Chip: RK322H Upgrade Prompt	. 00	Success	
toryTool(Release Vesion) v1.72.2	Device List Bebug KAT Nexus 11_20221109.00 Device List My Computer My Computer Port[1] Port[2] Port[3] Port[4]	Device Type	ID In	Exit Firmware Ver: b. 0 Loader Ver: 2. 32 Chip: RK322H Upgrade Prompt	• 00	Success	
toryTool(Release Vesion) v1.72.2	Upgrade Restore debug: KAT_Nexus_11_20221109.00 Device List Image: My Computer Image: Wy Computer	Device Type	ID Languag	Exit Firmware Ver: b. 0 Loader Ver: 2. 32 Chip: RK322H Upgrade Prompt		Success ^	
toryTool(Release Vesion) v1.72.2	Upgrade Restore debug: KAT_Nexus_11_20221109.00 Device List Image: Second Se	Device Type	ID Languag	Exit Firmware Ver: b. 0 Loader Ver: 2. 32 Chip: RK322H Upgrade Prompt		Success ^	
toryTool(Release Vesion) v1.72.2	Upgrade Restore 3ebug, KAT_Nexus_11_20221109.00 00 Device List	Device Type	ID In the second	Exit Firmware Ver: b. 0 Loader Ver: 2. 32 Chip: RK322H Upgrade Prompt		Success ^	
toryTool(Release Vesion) v1.72.2	Upgrade Restore Bebug RAT Nexus 11 20221109.00 Oevice List Device List	Device Type	ID Insues	Exit Firmware Ver: b. 0 Loader Ver: 2. 32 Chip: RK322H Upgrade Prompt		Success	
toryTool(Release Vesion) v1.72.2	Upgrade Restore iebug, KAT_Nexus_11_20221109.00 Device List Device List My Computer Image: Second Se	Device Type	ID In	Exit Firmware Ver: b. 0 Loader Ver: 2. 32 Chip: RK322H Upgrade Prompt	. 00	Success	
toryTool(Release Vesion) v1.72.2	Upgrade Restore Hebug KAT Nexus 11_20221109.00 Device List Image: State Sta	Device Type	ID Insues	Exit Firmware Ver: b. 0 Loader Ver: 2. 32 Chip: RK322H Upgrade Prompt		Success	
toryTool(Release Vesion) v1.72.2	Upgrade Restore Bebug KAT Nexus 11 20221109.00 Device List Image: Second Sec	Demo	ID III IIIIIIIIIIIIIIIIIIIIIIIIIIIIIII	Exit Firmware Ver: b. 0 Loader Ver: 2. 32 Chip: RK322H Upgrade Prompt		Success ^	
toryTool(Release Vesion) v1.72.2	Upgrade Restore debus KAT Nexus 11 20221109.00 debus KAT Nexus 11 20221109.00 Device List	Device Type	ID Instance	Exit Firmware Ver: b. 0 Loader Ver: 2. 32 Chip: RK322H Upgrade Prompt		Success ^	
toryTool(Release Vesion) v1.72.2	Upgrade Restore debug: KAT_Nexus_11_20221109.00 Device List Bebug: Washington State Port[1] Bebug: Washington State Port[3] Bebug: Washington State Port[4] Bebug: Washington State Port[4] Bebug: Washington State Port[6] Bebug: Washi	Device Type	ID Languag	Exit Firmware Ver: b. 0 Loader Ver: 2. 32 Chip: RK322H Upgrade Prompt		Success ^	
yTool(Release Vesion) v1.72.2 Firmware Stop re Dr. update: R65015 user Fail	Upgrade Restore debug_KAT_Nexus_11_20221109.00 Device List My Computer My Computer E RootHub20 G W RootHub20	Desice Type	ID	Exit Firmware Ver: b. 0 Loader Ver: 2. 32 Chip: RK322H Upgrade Prompt	. 00 ID	Success	
toryTool(Release Vesion) v1.72.2 Firmware Stop ware DAupdate RK3315 user mo Fail	Upgrade Restore debug: KAT_Nexus_11_20221109.00 00 Device List	Device Type	ID Languag	Exit Firmware Ver: b. 0 Loader Ver: 2. 32 Chip: RK322H Upgrade Prompt		Success ^	
toryTool(Release Vesion) v1.72.2 Firmware Stop wware	Upgrade Restore Sebug, KAT, Nexus, 11_20221109, 00 Device List Device List Device List My Computer Optimized Sebug, 2000 Optimized Sebug, 2000 Port[1] Port[2] Port[3] Port[4] Port[5] Port[5] Port[6] Port[7] Port[8] Port[8] Port[8]	Device Type	ID Instance	Exit Firmware Ver: b. 0 Loader Ver: 2. 32 Chip: RK322H Upgrade Prompt		Success ^	
toryTool(Release Vesion) v1.72.2	Upgrade Restore Hebug, KAT, Nexus, 11, 20221109, 00 Device List Device List My Computer My Computer Port[1] Port[2] Port[3] Port[3] Port[3] Port[4] Port[6] Port[6] Port[8] Port[8] Port[8] Port[8] Port[9]	Device Type	ID III	Exit Firmware Ver: b. 0 Loader Ver: 2. 32 Chip: RK322H Upgrade Prompt		Success	
toryTool(Release Vesion) v1.72.2	Upgrade Restore debug: KAT_Nexus_11_20221109.00 Device List Image: Second Se	Device Type	ID Languag	Exit Firmware Ver: b. 0 Loader Ver: 2. 32 Chip: RK322H Upgrade Prompt		Success ^	
toryTool(Release Vesion) v1.72.2	Upgrade • Restore Hebug, KAT, Nexus, 11, 20221109, 00 Device List Image: State Sta	Device Type	ID III	Exit Firmware Ver: b. 0 Loader Ver: 2. 32 Chip: RK322H Upgrade Prompt		Success	
toryTool(Release Vesion) v1.72.2 Firmware Stop Nware ONUpdate R03318_user amo Fail	Upgrade Restore Bebug KAT Nexus 11 20221109.00 O Device List Image: Computer Image: Computer Image: Computer Im	Device Type	ID Insues	Exit Firmware Ver: b. 0 Loader Ver: 2. 32 Chip: RK322H Upgrade Prompt		Success	
toryTool(Release Vesion) v1.72.2 Firmware Stop wware D. Vupdate RK3315_user eno D Fail /	Upgrade Restore debug: KAT_Nexus_11_20221109.00 Device List	Device Type	ID In the second	Exit Firmware Ver: b. 0 Loader Ver: 2. 32 Chip: RK322H Upgrade Prompt		Success ^	
toryTool(Release Vesion) v1.72.2	Upgrade Restore debug: KAT_Nexus_11_20221109.00 Device List Image: Second Se	Device Type	ID Innuary	Exit Firmware Ver: b. 0 Loader Ver: 2. 32 Chip: RK322H Upgrade Prompt		Success ^	
toryTool(Release Vesion) v1.72.2	Upgrade Restore Bebug KAT Nexus 11 20221109.00 Device List Image: Second Sec	Demo	ID III IIIIIIIIIIIIIIIIIIIIIIIIIIIIIII	Exit Firmware Ver: b. 0 Loader Ver: 2. 32 Chip: RK322H Upgrade Prompt		Success A	
toryTool(Release Vesion) v1.72.2 Firmware 5 top mware 7 top mware 7 top mware 7 top mware 7 top Tail / '	Upgrade Restore Sebug, KAT, Nexus, 11_20221109.00 Device List Image: Sebug, KAT, Nexus, 11_20221109.00 Image: Sebug, KAT, Nexus, 11_20221109.00 Image: Sebug, KAT, Nexus, 11_20221109.00 Image: Sebug, KAT, Nexus, 11_20221109.00 Image: Sebug, KAT, Nexus, 11_20221109.00 Image: Sebug, KAT, Nexus, 11_20221109.00 Image: Sebug, KAT, Nexus, 11_20221109.00 Image: Sebug, KAT, Nexus, 11_20221109.00 Image: Sebug, KAT, Nexus, 11_20221109.00 Image: Sebug, KAT, Nexus, 11_20221109.00 Image: Sebug, KAT, Nexus, 11_20221109.00 Image: Sebug, KAT, Nexus, 11_20221109.00 Image: Sebug, KAT, Nexus, 11_20221109.00 Image: Sebug, KAT, Nexus, 11_20221109.00 Image: Sebug, KAT, Nexus, 11_20221109.00 Image: Sebug, KAT, Nexus, 11_20221109.00 Image: Sebug, KAT, Nexus, 11_20221109.00 Image: Sebug, KAT, Nexus, 11_20221109.00 Image: Sebug, KAT, Nexus, 11_20221109.00 Image: Sebug, KAT, Nexus, 11_20221109.00 Image: Sebug, KAT, Nexus, 11_20221109.00 Image: Sebug, KAT, Nexus, 11_20221109.00 Image: Sebug, KAT, Nexus, 11_20221109.00 Image: Sebug, KAT, Nexus, 11_20221109.00 Image: Sebug, KAT, Nexus, 11_20221109.00 Image: Sebug, KAT, Nexus, 11_20221109.00 Image: Sebug, KAT, Nexus, 11_20221100 Image: Sebug, KAT, Nexus, 11_2021109.00	Device Type	ID Instance	Exit Firmware Ver: b. 0 Loader Ver: 2. 32 Chip: RK322H Upgrade Prompt		Success ^	
toryTool(Release Vesion) v1.72.2	Upgrade Restore Bebug KAT Nexus 11_20221109.00 Device List Image: Second Sec	Device Type	ID III IIIIIIIIIIIIIIIIIIIIIIIIIIIIIII	Exit Firmware Ver: b. 0 Loader Ver: 2. 32 Chip: RK322H Upgrade Prompt		Success A	
toryTool(Release Vesion) v1.72.2 Firmware 0 Stop mware 0 Update RK3315 user eno D Fail /	Upgrade Restore debug: KAT_Nexus_11_20221109.00 Device List	Device Type	ID Instance	Exit Firmware Ver: b. 0 Loader Ver: 2. 32 Chip: RK322H Upgrade Prompt		Success ^	
toryTool(Release Vesion) v1.72.2	Upgrade Restore Bebus KAT Nexus 11 20221109.00 O Device List Image: Computer Image: Computer Image: Computer Im	Device Type	ID I	Exit Firmware Ver: b. 0 Loader Ver: 2. 32 Chip: RK322H Upgrade Prompt		Success A	
toryTool(Release Vesion) v1.72.2	Upgrade Restore Hebug KAT Nexus 11_20221109.00 Device List Image: State Sta	Device Type	ID Construction of the second	Exit Firmware Ver: b. 0 Loader Ver: 2. 32 Chip: RK322H Upgrade Prompt	. 00	Success	
toryTool(Release Vesion) v1.72.2	Upgrade Restore debug: KAT_Nexus_11_20221109.00 Device List Image: Second Se	Device Type	ID Construction of the second	Exit Firmware Ver: b. 0 Loader Ver: 2. 32 Chip: RK322H Upgrade Prompt	• 00	Success	
toryTool(Release Vesion) v1.72.2	Upgrade Restore Bebug KAT Nexus 11 20221109.00 O Device List Image: Computer Image: Computer Image: Computer Im	Device Type	ID Construction of the second	Exit Firmware Ver: b. 0 Loader Ver: 2. 32 Chip: RK322H Upgrade Prompt	• 00	Success A	
toryTool(Release Vesion) v1.72.2	Upgrade Restore Hebug KAT Nexus 11_20221109.00 Device List Image: State of the state	Device Type	ID Construction of the second	Exit Firmware Ver: b. 0 Loader Ver: 2. 32 Chip: RK322H Upgrade Prompt	. 00	Success	
toryTool(Release Vesion) v1.72.2 Firmware 0 Stop wware 0 Update NK3315 user ano 0 Fail / rad: First use, Tag USB port: p	Upgrade Restore Sebug KAT Nexus 11 20221109.00 Device List Image: Sebug KAT Nexus 11 20221109.00 Image: Sebug KAT Nexus 11 20221109.00 Image: Sebug KAT Nexus 11 20221109.00 Image: Sebug KAT Nexus 11 20221109.00 Image: Sebug KAT Nexus 11 20221109.00 Image: Sebug KAT Nexus 11 20221109.00 Image: Sebug KAT Nexus 11 20221109.00 Image: Sebug KAT Nexus 11 20221109.00 Image: Sebug KAT Nexus 11 20221109.00 Image: Sebug KAT Nexus 11 20221109.00 Image: Sebug KAT Nexus 11 20221109.00 Image: Sebug KAT Nexus 11 20221109.00 Image: Sebug KAT Nexus 11 20221109.00 Image: Sebug KAT Nexus 11 20221109.00 Image: Sebug KAT Nexus 11 20221109.00 Image: Sebug KAT Nexus 11 20221109.00 Image: Sebug KAT Nexus 11 20221109.00 Image: Sebug KAT Nexus 11 20221109.00 Image: Sebug KAT Nexus 11 20221109.00 Image: Sebug KAT Nexus 11 20221109.00 Image: Sebug KAT Nexus 11 20221109.00 Image: Sebug KAT Nexus 11 20221109.00 Image: Sebug KAT Nexus 11 20221109.00 Image: Sebug KAT Nexus 11 20221109.00 Image: Sebug KAT Nexus 11 20221109.00 Image: Sebug KAT Nexus 11 20221109.00 Image: Sebug KAT Nexus 11 20221109.00 Image: Sebug KAT Nexus 11 20221109.00 Image: Sebug KAT Nexus 11 20221109.00 <	Device Type	ID I	Exit Firmware Ver: b. 0 Loader Ver: 2. 32 Chip: RK 322H Upgrade Prompt	.00	Success	
toryTool(Release Vesion) v1.72.2	Upgrade • Restore Bebug KAT Nexus 11 20221109.00 Device List • My Computer • My Computer • Port[1] • Port[2] • • Port[3] • • Port[4] • • Port[6] • • Port[6] • • Port[1] • • • Port[1] • • Port[2] • • • • Port[2] • • • Port[6] • • • • • • • • • • • • •	Device Type	ID I	Exit Firmware Ver: b. 0 Loader Ver: 2. 32 Chip: RK322H Upgrade Prompt	.00	Success	
ttoryTool(Release Vesion) v1.72.2 Firmware Stop mware Stop mware Fail D Fail C Fail First use, Tag USB port: p After pluging device in,	Upgrade Restore Sebug KAT Nexus 11 20221109.00 Device List My Computer My Port[3] My Port[3] <td>Device Type</td> <td>ID ID I</td> <td>Exit Firmware Ver: b. 0 Loader Ver: 2. 32 Chip: RK 322H Upgrade Prompt</td> <td>.00</td> <td>Success</td> <td></td>	Device Type	ID I	Exit Firmware Ver: b. 0 Loader Ver: 2. 32 Chip: RK 322H Upgrade Prompt	.00	Success	
ctoryTool(Release Vesion) v1.72.2 First use, Tag USB port: p After pluging device in,	Upgrade Restore Device List My Computer Port[1] Port[2] Port[3] Port[4] Port[6] Port[6] Port[7] Port[1] Port[2] Port[3] Port[6] Port[6] Port[6] Port[7] Port[7] Port[8] Port[9] Image: Port[9] Image: Port[9]	Device Type	ID I	Exit Firmware Ver: b. 0 Loader Ver: 2. 32 Chip: RK322H Upgrade Prompt	.00	Success A	VIS. VIS. Test
ctoryTool(Release Vesion) v1.72.2 Firmware Stop mware Mupdete RK3316 user D Fail / D Fail / Zard: First use, Tag USB port: p After pluging device in, led is green, plug device	Upgrade Restore Hebug KAT Nexus 11_20221109.00 Device List My Computer My Computer My Computer Port[1] Port[2] Port[3] Port[4] Port[6] Port[6] Port[7] Port[8] Port[9] Port[9]	Device Type	Delta reguage	Exit Firmware Ver: b. 0 Loader Ver: 2. 32 Chip: RK322H Upgrade Prompt	.00	Success Success	

automatically, you can release the Reset button.

杭州虚现科技有限公司 Copyright © 2017 Hangzhou Virtual And Reality Technology Co., LTD. 11, Firmware upgrade takes 3-5 minutes, when the following prompt appears, it

Firmware	Stop Upgrade © Restore	Demo	Lang	uage 🌩 Exit		
Firmware D:\update	RK3318_userdebug_KAT_Nexus_11_20221109.0	014. img		Firmware Ver:b.	0.00	
T TIMWAR C				Loader Ver: 2.32		
Demo				CL : DV0000		
Demo				Chip: KK322H		
ID Fa	II Device List	Device Type	ID	Upgrade Prompt	1	D Succe
13 aload Firm	rare Succ 🛛 🖃 🐺 My Computer				^	
	BootHub20					
	Port[4]					
	Port[5]					
	Port[6]					
	RootHub20					
					_	
					_	
	Port[4]				_	
					_	
	Port[b]		10		_	
		Maskrom	13	Download Firmware Succes	s	

124

P.

means the update is successful.



A A